

South Steel He Care for Comment Steel Stee

FIG.3





FIG.4



## FIG.5

Prevention against explosion Prevention against explosion is backed up by emergency extinguishing. Electrical protections of the transformers earth fault differential Current Buchholz surge protection and explosion detector Explosion detector integrated with the integrated with the One of the electrica. rupture discs of the rupture disc of protections high-and low-voltage the transformer feed-throughs, and on-load tap changers Conservator Storage valve closed and Prevention of explosion Nitrogen is immediately injected into the enclosure, into the on-load tap changers and into the feed throughs in order to: Stop the production of hydrogen Discharge the explosive gases Prevent oxygen from entering Cool the dielectric oil Limit damage

FIG.6

